

Daily Track Inspection

Name A. Rabette S. Sell Date 8-1-17 Page of

Watchman A. Rabe He S. Sell WO# 3017890

Inspection From Coldspring To Camden - But Penn

[illegible][illegible]

Were switches in area inspected? YES ✓ NO

Is this a Special Inspection? YES _____ NO ✓

Reason for Inspection _____


Track Inspectors Signature

Jann Reava
Supervisory Certification

8/2/17
Date



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3017890

TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
s3 8-1-17 No new defects noted in area.

Alias:		Location:	CHAIN_MARKER! LT Rail Chain Markers	Status:	
Asset:		Year:		Manufacturer:	
Serial Number:				License:	
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	8/2/17
Target Finish:	8/2/17
Actual Start:	8/1/17
Actual Finish:	8/1/17
Report Date:	7/29/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-#####-0901-#####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48477

Job Plan:	2956
Job Desc:	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S		



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3017890 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
s3 8-1-17 No new defects noted in area.

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR			SSELL				10		N		08:00	00:00	212.00
AREPAIR			ARABETT				10		N		08:00	00:00	217.36
Total Actual Labor:													429.36



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3017890 TEAM ONE - SECT 3: CS/CY/PENN - CM 235N TO 16S
s3 8-1-17 No new defects noted in area.

Task IDs									
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?	
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE							N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE							N

Date Completed

Completed By

Supervisor



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3017896 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
s5 8-2-17 Riding inspection due to manpower shortage. No new defects noted in area.

Alias:	Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:
Asset:	Year:	Manufacturer:	Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters: Description Unit of Measure Last Reading Date Last Reading
CI: Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	8/3/17
Target Finish:	8/3/17
Actual Start:	8/2/17
Actual Finish:	8/2/17
Report Date:	7/29/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-#####-0901-#####-#####-####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48480

Job Plan:	2960
Job Desc:	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD		



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3017896

TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD

s5 8-2-17 Riding inspection due to manpower shortage. No new defects noted in area.

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	AREPAIR		ARABETT						N		08:00	00:00	217.36
	AREPAIR		SSELL				10		N		00:00	06:00	238.50
	AREPAIR		ARABETT				10		N		00:00	06:00	244.53
	AREPAIR		SSELL						N		08:00	00:00	212.00
Total Actual Labor:													912.39



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3017896 TEAM ONE - SECT 5 - LINT/CROM/BWI CM 355S/488S & CROMYARD
s5 8-2-17 Riding inspection due to manpower shortage. No new defects noted in area.

Task IDs								
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed Completed By Supervisor

Daily Track Inspection

Inspection From Linthicum To Cromwell - BWI

[illegible][illegible]

Reason for Inspection _____

Track Inspectors Signature

Janna Reaver
Supervisory Certification

8/3/17
Date



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-B

WO # 3017871

TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N

no new defects noted in area.

Alias:		Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	8/2/17
Target Finish:	8/2/17
Actual Start:	8/1/17
Actual Finish:	8/1/17
Report Date:	7/29/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270- #####-0901-##### #####-####-#### #####-000-30-00
Warranty Situation Present?	N
PM Num:	48476

Job Plan:	2955
Job Desc:	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N		



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3017871 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
no new defects noted in area.

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR			GLAM						N		08:00	00:00	210.32
AREPAIR			MPOLLAF						N		08:00	00:00	210.32
Total Actual Labor:													420.64



MD - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3017871 TEAM TWO - SECT 2: LU/CS - CM 586N TO 235N
no new defects noted in area.

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

012



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-B

WO # 3017893

TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S

Track inspection complete, no new defects noted

Alias:		Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	8/3/17
Target Finish:	8/3/17
Actual Start:	8/3/17
Actual Finish:	8/3/17
Report Date:	7/29/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270- #####-0901-##### #####-####-#### #####-000-30-00
Warranty Situation Present?	N
PM Num:	48479

Job Plan:	2959
Job Desc:	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S		



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3017893 TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
Track inspection complete, no new defects noted

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
20	AREPAIR	MPOLLAF					10		N		00:00	06:00	236.61
	AREPAIR	MPOLLAF							N		08:00	00:00	210.32
Total Actual Labor:													446.93



MD - Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3017893 TEAM TWO - SECT 4: CY/LINT - CM 16S TO 355S
Track inspection complete, no new defects noted

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Daily Track Inspection

Name Rollard

Date 8-2-17 Page 1 of 1

Watchman

WØ# 3817893

Inspection From Linthicum

To Camden yards

[illegible]

Items

Comments

[illegible]

Were switches in area inspected?

YES

NO

Is this a Special Inspection?

YES

NO

Reason for Inspection

Track Inspectors Signature

Supervisory Certification

/Date

Light Rail MOW

Daily Track Inspection

Name Billard Date 8-3-201 Page 1 of 1

Watchman Lam WO# _____

Inspection From TK1 cm 204+15 To _____

Items	Exception Chain Marker No.		Track	Rail	Switch	Codes		Status	Repair	W.O
	From	To	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N	#
1.	204+15		1			T304	34P	Y	N	
2.										
3.										
4.										
5.										
6.										
7.										
8.										
9.										
10.										
11.										
12.										

COPY

Items	Comments
1	3 cubs and ties are being undermined. there is ballast missing from under the ties 10" down and 23" from the end of the ties, this causing a void under the track and causing the track to pump 1".
	A 15 mph speed restriction was put on from Patapsco to Baltimore Highlands TK1

Were switches in area inspected? YES _____ NO ✓

Is this a Special Inspection? YES ✓ NO _____

Reason for Inspection undermined track

[Signature]
Track Inspectors Signature

[Signature]
Supervisory Certification

8/4/17
Date

Name A. Ribette S. Sell Date 8-3-17 Page of

(Please Print)
 Watchman A. Robette S. Sell

WO# 3016535

Inspected From Luther Ville

To Coldspring

[illegible]

COPY

[illegible]

Were switches in the area inspected?

Yes ☒

No _____

Is this a Special Inspection?

Yes _____

No ☒

Reason for Special Inspection?

Q. the Rabbit

Track Inspectors Signature

Jann Reaver
Supervisory Certification

Supervisory Certification

8/4/17

Date _____

Daily Track Inspection

Inspection From _____ To _____

COPY

Comments

[illegible]

Reason for Inspection _____

8/4/17
Date

0/3



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-A

WO # 3016535

TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N
s2 8-3-17 No new defects noted in area.

Alias:		Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	8/3/17
Target Finish:	8/3/17
Actual Start:	8/3/17
Actual Finish:	8/3/17
Report Date:	7/28/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270- #####-0901-##### #####-####-#### #####-000-30-00
Warranty Situation Present?	N
PM Num:	48473

Job Plan:	2954
Job Desc:	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification				
Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N		



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3016535 TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N
s2 8-3-17 No new defects noted in area.

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR			SSELL				10		N		08:00	00:00	212.00
AREPAIR			ARABETT				10		N		08:00	00:00	217.36
Total Actual Labor:													429.36



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3016535 TEAM ONE - SECT 2: LU/CS - CM 586N TO 235N
s2 8-3-17 No new defects noted in area.

Task IDs									
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?	
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE							N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE							N

Date Completed

Completed By

Supervisor

Date _____



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-B

WO # 3016507

TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N
no new defects noted in area

Alias:		Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:	
Asset:	Year:	Manufacturer:		Type:	
Serial Number:		License:			
Service Address:	1155 344 West North Ave, Baltimore MD				

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	8/3/17
Target Finish:	8/3/17
Actual Start:	8/3/17
Actual Finish:	8/3/17
Report Date:	7/28/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270- #####-0901-##### #####-####-#### #####-000-30-00
Warranty Situation Present?	N
PM Num:	48474

Job Plan:	2953
Job Desc:	TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N		



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3016507 TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N
no new defects noted in area

Actual Labor

Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	AREPAIR		GLAM						N		08:00	00:00	210.32
	AREPAIR		MPOLLAF						N		08:00	00:00	210.32
Total Actual Labor:													420.64



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3016507 TEAM TWO - SECT 1: HV/LU - CM 902N TO 586N
no new defects noted in area

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

00/4



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

Crew ID: DAY-B

WO # 3029111 TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD
no new defects noted in area

Alias:	Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:
Asset:	Year:	Manufacturer:	Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters: Description Unit of Measure Last Reading Date Last Reading

CI:

Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	8/11/17
Target Finish:	8/11/17
Actual Start:	8/4/17
Actual Finish:	8/4/17
Report Date:	8/4/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-####-05270- #####-0901-##### #####-####-#### #####-000-30-00
Warranty Situation Present?	N
PM Num:	48478

Job Plan:	2957
Job Desc:	TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification	Attribute	Description	ALN Value	Numeric Value	Unit of Measure
	LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD			



- Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3029111 TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD
no new defects noted in area

Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
AREPAIR			GLAM						N		08:00	00:00	210.32
AREPAIR			MPOLLAF						N		08:00	00:00	210.32
Total Actual Labor:													420.64



Maximo

Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3029111 TEAM TWO - SECT 3 - CM 235N/16S AND NORTH AVE YD
no new defects noted in area

Task IDs

Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE						N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE						N

Date Completed

Completed By

Supervisor

Date _____

To Cromwell BwI

COPY

no new defects noted in AREA

No _____

No ☒

8/7/17
Date

0/5



Maryland Department of Transportation

Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3021771 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
no new defects noted in area

Alias:	Location:	CHAIN_MARKER: LT Rail Chain Markers	Status:
Asset:	Year:	Manufacturer:	Type:
Serial Number:	License:		
Service Address:	1155 344 West North Ave, Baltimore MD		

Meters: Description Unit of Measure Last Reading Date Last Reading
CI: Mileage Meter:

Sched Start:	
Sched Finish:	
Target Start:	8/9/17
Target Finish:	8/9/17
Actual Start:	8/5/17
Actual Finish:	8/5/17
Report Date:	8/1/17
Reported By:	MTACRON
Requestor of Work:	

Site:	LTRAIL
Priority:	1
Work Type:	PM
Status:	CLOSE
Parent:	
Person Group:	MTA527
GL Account:	J05-#####-05270-#####-0901-#####-#####-####-#####-000-30-00
Warranty Situation Present?	N
PM Num:	48481

Job Plan:	2961
Job Desc:	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
Supervisor:	
Lead:	JREAVES3
Owner:	
Owner Group:	
Service:	
Service Group:	
Classification:	2732
Part Failure:	

Specification

Attribute	Description	ALN Value	Numeric Value	Unit of Measure
LTRAIL_DESCRIPTION	LTRAIL_DESCRIPTION	TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD		



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3021771		TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD no new defects noted in area											
Actual Labor													
Task ID	Craft	Skill Level	Labor	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty	Contract Num	Regular Hours	Premium Hours	Line Cost
	AREPAIR		GLAM						N		08:00	00:00	210.32
	AREPAIR		MPOLLAF						N		08:00	00:00	210.32
Total Actual Labor:													420.64



Work Order Details (Tr)

Org ID: MTA
Site: LTRAIL

WO # 3021771 TEAM TWO - SECT 5: LINT/CROM/BWI CM 355S TO 488S & CROMYARD
no new defects noted in area

Task IDs									
Task ID	Description	Status	Component	Position	Reason for Repair	Work Accomplished	Part Failure	Warranty?	
10	ESTABLISH ON TRACK SAFETY PER RPW GUIDELINES	CLOSE							N
20	INSPECT TRACK PER BALT LR STANDARD PROCEDURES	CLOSE							N

Date Completed

Completed By

Supervisor